

Service Bulletin TM-10-01

OPTIONAL

Affected propeller types: All NEUFORM 3-Blade-Variable-Pitch Propellers, R2-Series

Subject: Increase of check time intervall according to operating manual from 500 hrs (3 years) to 750 hrs (5 years).

Reason: An analysis of findings of all previous 500 hrs-checks justifies an increase of the check time interval up to 750 hrs or 5 years depending on what occurs first.

Measures: **Replacement of Operating Manual** (NEUFORM 3-Blade-Variable-Pitch Propellers, R2-Series) by the version of 28 APRIL 2010 or newer. The current version is available for download under:

<http://www.neuform-propellers.com/en/propellers/service-and-consultation/downloads>

Further applicable documents:

Operating Manual (NEUFORM 3-Blade-Variable-Pitch Propellers, R2-Series) dated 28.04.10

Note:

1. The increase of the check time intervall explicitly applies as well to all already delivered propellers of this type.

2. The *Assembly- and Maintenance Manual* (NEUFORM 3-Blade-Variable-Pitch Propellers, R2-Series) has been updated in line with this service bulletin as well (dated 28.04.10). It can be requested at NEUFORM.

